





Assembly

Stressless® Dining


D100



Scan me for assembly video




T30 #99230316



4 x

#990005707



#75007922





2 x

#1997809




8 x






#990000999








Scan me for assembly video










Scan me for assembly video






T30 #99230316



4 x

#990005707






#75007922





Tighten the bolts again
after some months



Scan me for assembly video







STRESSLESS.COM

Ekornes AS, Industrivegen 1, N-6222 Ikkornnes

Tel.: (+47) 70 25 52 00

E-mail: office.no@ekornes.com