





# Assembly

## Stressless® Dining

### D200





Scan me for assembly video





Scan me for assembly video

1



2



#1997809









#990000999

T30 #99230316






Tighten the bolts again  
after some months











Scan me for assembly video






T30 #99230316

4 x



#990005707






#75007922






Tighten the bolts again  
after some months



Scan me for assembly video







STRESSLESS.COM

Ekornes AS, Industrivegen 1, N-6222 Ikkornnes  
Tel.: (+47) 70 25 52 00  
E-mail: office.no@ekornes.com