

Assembly instruction Stressless® Home Office

Steel base



5x
1997303



4x



1x
1997213











2x
990002626



2x
1997304

1x
1997000



990002271

