





Assembly

Stressless® Dining


D200



Scan me for assembly video





T30 #99230316




2 x

#1997809



4 x

#990005707




#75007922



8 x



#990000999





Scan me for assembly video

1



2

2 x




#1997809

8 x









#990000999

T30 #99230316






Tighten the bolts again
after some months










Scan me for assembly video





#990005707




T30 #99230316

4 x



#990005707






#75007922





Tighten the bolts again
after some months



Scan me for assembly video







STRESSLESS.COM

Ekornes AS, Industrivegen 1, N-6222 Ikkornes

Tel.: (+47) 70 25 52 00

E-mail: office.no@ekornes.com